
















GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
<b>2B9-210</b>  <u>Flexmember</u> 578-92-3-202		<b>578-92-8-040</b> 	<b>ASA-92-6-010</b> 	<b>Firestone</b> 6908 <b>Triangle</b> 4362 <b>Watson &amp; Chalin</b> AS-0035
<b>2B9-218</b>  <u>Flexmember</u> 578-92-3-206		<b>ASA-92-8-113</b> 	<b>ASA-92-6-010</b> 	<b>Firestone</b> 6927 <b>Langes</b>  <b>Load Guard</b> SC2072 <b>Navistar</b> 1685176C1 <b>Reyco</b> 12906-01 12906-02 <b>Taurus</b> AS218-6927
<b>2B9-225</b>  <u>Flexmember</u> 578-92-3-202		<b>ASA-92-8-117</b> 	<b>ASA-92-6-044</b> 	<b>Misner Brake System</b>  <b>Thraul Davis Rail Car</b>
<b>2B9-229</b>  <u>Flexmember</u> 578-92-3-202		<b>ASA-92-8-113</b> 	<b>ASA-92-6-077</b> 	<b>Firestone</b> 6897 <b>Triangle</b> 4505 <b>Watson &amp; Chalin</b> AS-0058
<b>2B9-230</b>  <u>Flexmember</u> 578-92-3-202		<b>ASA-92-8-113</b> 	<b>ASA-92-6-044</b> 	<b>Firestone</b> 6940 <b>Langes</b>  <b>Triangle</b> 4450